1.34	· ·			00/(1
50X1		COMPTENSTAL		REPORT NO.
COUNTRY	ussr (rsfsr/	leorgian SSR)		DATE DISTR. 8 Sept. 1954
SUBJECT	Rostov-Baku Railroad Line			NO. OF PAGES 4
DATE OF INFORMATION			50X1	REFERENCES:
PLACE ACQ	DUIRED	,		
			ORMANTION	
		THIS IS UNEVALUATED INF	ORMATION	
COLIDCI				

50X1

50X1

50X1

Train Density

This double-track line was the main line between Rostov and Baku and connected the following cities with almost hourly passenger and freight traffic: Mineralnyye Vody, Groznyy, Derbent, and Makhachkala. Source was not able to give the extent of traffic on this line.

Signaling and Train Control Systems

the train control or signaling systems in

operation on any lines in the USSR. received while attending 50X1

50X1

system was based on information

All switching signals within rail yards were operated manually. Signal bars had round discs, about 20 cm. in diameter, with a black arrow inside pointing in the direction of movement. Red and yellow blinker lights, controlled from the main switching house in the yard, showed the right of way.

Along main lines a block system of braking was used; Source believed that it was an automatic braking system. The engine in some manner engaged a magnetic field at a certain point along the line and signaled the engineer to apply the brakes.

All grades, curves, and crossings were marked; in the case of curves, Source believed that the direction and degree of curve were indicated. All bridges were marked with clearance signs, and in some cases guards controlled traffic at these points if necessary.

CONFIDENTIAL

No information

9. New Construction and Major Repairs

New construction and major repairs on the Rostov-Baku line included double tracking and electrification. To the best of Source's knowledge, none of the line was electrified. No other information.

10. no information on any other railroad line.

1 Encl:

50X1

A. Rostov, Lenin Locomotive Repair Plant in Rostov, USSR

CONFIDENTIAL

CONFIDENTIAL 50X1


CONFIDENTIAL

Enclosure A

Rostov, Lenin Locomotive Repair Plant in Rostov, USSR

Note: This plant was located within the main railroad station in ROSTOV.

Memory sketch; not to scale



50X1

50X1

CONFIDENTIAL

Enclosure A

Rostov, Lenin Locomotive Repair Plant in Rostov, USSR

LEGEND

- 1. Locomotive repair and paint shop: 1-story brick bldg, about 500 x 500 m, with a flat roof. This was the main section of the plant, and operated 24 hours daily. All locomotive repairs were done here; large overhead cranes in the shop were used to dismantle locomotives. About 1000 people worked in this section.
- Unsalvageable locomotive park: 10-20 partially dismantled locomotives were usually parked here. Parts from them were used in the repair shop.
- 3. Machine shop: dimensions unknown.
- 4. Parts room and storehouse for machine parts.
- Locomotive tender repair shop: shed-type bldg, about 100 x 100 m.
- 6. Gate: used by locomotives for entrance to repair plant. Factory guard posted here 24 hours daily to control traffic.
- Instrument and brake repair shop: 2-story brick bldg, about 50 x 10 m.
- 8. Gate: factory guard posted at all times.
- 9. Gate: same as item 8.
- 10. Gate: same as item 8.
- 11. Factory dispensary: brick bldg, about 50 x 10 m.
- 12. Plant sheds: used for storage of parts and metal.
- 13. Plant administration office: 3-story brick bldg. 20 x 20 m. All administrative offices were in this building.

CONFIDENTIAL